

A

Photo showing steepness of western side of spit channel, looking north to the island.



B

Spit on southern end of Selingan, looking south, low tide



C

Looking south to end of breakwater and island. Mid high water.




D

Looking north to end of breakwater.
Mid high water. Accretion to the north
Is since the breakwater was installed in
Oct-Nov 2005.



D2

Accretion due to breakwater, looking northeast.
Low water, nearly at max low tide.



E

Looking north to apex of curve in the beach. This beach used to be wider.



F

Looking north to top of island and rocky outcrop.

